

## COM 2 COMPUTERS – OSHA LOG

Citation # / Item # with CFR	Description of Citation	Required Abatement Date
Citation #1 / Item #1 29 CFR 1910.135(a) (1)	Employer did not insure that each affected employee wore a helmet when working in areas where there was a potential for injuries to the head from falling objects:	Corrected During Inspection
Citation #1 / Item #2 29 CFR 1910.176 (b)	Material stored in tiers was not stacked, blocked, interlocked or limited in height so it was stable and secure against sliding or collapse.	Corrected
Citation #1 / Item #3 29 CFR 1910.212 (a) (1)	One or more methods of machine guarding was not provided to protect the operator and other employees in machine area from hazards such as those created by point of operation, ignoring nip points, rotating parts, flying chips and sparks:	Corrected
Citation #1 / Item #4a 29 CFR 1910.1025 (c) (1)	Employee(s) were exposed to lead concentrations greater than fifty micrograms per cubic meter of air averaged over an eight hour period:	Corrected

Citation # / Item # with CFR	Description of Citation	Required Abatement Date
Citation #1 / Item #4d 29 CFR 1910.1025 (f) (2) (i)	The employer did not implement a respiratory protection program in accordance with 29 CFR 1910.134(b) through (d) (except (d) (1) (iii), and (f) through (m) for each employee required by 29 CFR 1910.125 to use a respirator:	Corrected
Citation #1 / Item #5a 29 CFR 1910.1025 (d) (1) (ii)	Full shift (for at least 7 continuous hours) personal samples for lead were not collected including at least one sample for each shift for each job classification in each work area:	Corrected During Inspection
Citation #1 / Item #5b 29 CFR 1910.1025(d) (7)	Additional exposure monitoring was not conducted when there was a change in production, process, control or personnel, or any other reason to suspect a change that may have resulted in new or additional exposure to lead.	Corrected During Inspection
Citation #1 / Item #6 29 CFR 1910.1025 (g) (1)	Appropriate protective work clothing and equipment was not provided when employee(s) were exposed to lead above permissible exposure limit (PEL), without regard to the use of respirators, or where the possibility of skin or eye irritation existed.	Corrected
Citation #1 / Item #7a 29 CFR 1910.1025 (i) (2) (i)	Clean change rooms were not provided for employees exposed to lead in excess of permissible exposure limit (PEL), without regard to the use of respirators	Corrected
Citation #1 / Item #7b 29 CFR 1910.1025 (i) (3) (ii)	Shower facilities, in accordance with 29 CFR 1910.141 (d) (3), were not provided for employee(s) exposed to lead in excess of the permissible limit (PEL), without regard to the use of respirators.	Corrected

Citation # / Item # with CFR	Description of Citation	Required Abatement Date
Citation #1 / Item #7c 29 CFR 1910.1025 (i) (3) (i)	Employee(s) exposed to lead in excess of the permissible exposure limit (PEL), without regard to the use of respirators, were not required to shower at the end of the work shift:	Corrected
Citation #1 / Item #7d 29 CFR 1910.1025 (i) (3) (ii)	Shower facilities, in accordance with 29 VFR 1910.141 (d) (3), were not provided for employee(s) exposed to lead in excess of the permissible exposure limit (PEL), without regard to respirators.	Corrected
Citation #1 / Item #8a 29 CFR 1910.1025 (h) (1)	All surfaces were not maintained as free as practicable of accumulations of lead:	Corrected
Citation #1 / Item #8b 29 CFR 1910.1025 (h) (2) (i)	Floors and/or other surfaces where lead accumulations were cleaned by the use of an air compressor.	Corrected
Citation #1 / Item #8c 29 CFR 1910.1025 (h) (2) (ii)	Shoveling, sweeping or brushing methods were used to remove lead accumulations were vacuuming or other equally effective methods were available and feasible:	Corrected
Citation #1 / Item #9 29 CFR 1910.1025 (i) (4) (ii)	Lunchroom facilities for employee(s) exposed to lead in excess of the permissible exposure limit (PEL), without regard to the use of respirators, were not provided with a temperature controlled, positive pressure and filtered air supply and were not readily accessible to employees.	Corrected

Citation # / Item # with CFR	Description of Citation	Required Abatement Date
Citation #1 Item 11a 29 CFR 1910.1025 (l) (1) (ii)	The employer did not train each employee who is subject to exposure to lead at or above the action level, or for whom the possibility of skin or eye irritation exists, in accordance with the requirements of 29 CFR 1910.1025:	Corrected
Citation #1 Item 11b 29 CFR 1910.1025 (m) (2) (i)	Warning signs bearing legend: WARNING LEAD WORK AREA, POISON, NO SMOKING OR EATING, were not posted in each area where permissible exposure limit (PEL) was exceeded:	Corrected
Citation #1 Item 11c 29 CFR 1910.1200 (h) (1)	The employer did not provide employees with effective information and training on hazardous chemicals in their work area at the time of their initial assignment, and whenever a new physical or health hazard the employees had not previously been trained about was introduced into their work area:	10/31/12